



Children's Product Certificate

Date of issue : Nov. 02, 2018

Importer / Suppliers Name : Bullet Line, LLC.

Importer Address : 6301 E 10th Ave.
Hialeah, FL 33013

Importer Contact : Compliance@bulletline.com

Item or SKU# : SM-9810

Description : Safety Clip-On Reflector

CPSIA Statement:

Bullet certifies that item listed above meets the standards under the Consumer Product Safety Improvement Act of 2008, together with any other applicable standard(s) or regulation(s) listed below based on our Testing and Inspection Program:

- CPSIA Section 101, Total Lead in Substrate Materials
- California Proposition 65, Phthalates (DBP, BBP, DEHP, DINP, DIDP, DnHP)
- 16 CFR 1307 Prohibition of Children's Toys and Child Care Articles Containing Specified Phthalates (DBP, BBP, DEHP, DINP, DHEXP / DnHP, DCHP, DIBP, DPENP)#
- 16 CFR 1500, Federal Hazardous Substances Act (FHSA), Mechanical Hazards
- 16 CFR 1500.3(c)(6)(vi), Flammability of Solids

Based on tests conducted by ANSECO GROUP (HK) LIMITED In Oct. 2018

This product was manufactured on one of the following dates (YYYY-MM-DD)

SM-9810BL

55030 : 2013-10-22	55985 : 2013-11-26	56400:2013-12-21	57707 : 2014-04-22
57231 : 2014-04-08	58186 : 2014-05-12	59350 : 2014-07-02	65264 : 2015-05-17
66540 : 2015-07-15	67296 : 2015-07-25	67889: 2015-08-20	69933 : 2015-11-27
70718 : 2016-01-09	71341 : 2016-03-01	72690 : 2016-04-23	75411 : 2016-09-15
75952 : 2016-10-17	76851 : 2016-11-30	82563 : 2017-07-12	M000000125: 2017-10-15
M000006194: 2018-6-25	M000006334: 2018-7-24	M000006838: 2018-8-11	

SM-9810GR

55258 : 2013-10-22	55665 : 2013-11-26	57972 : 2014-04-22	58488 : 2014-05-12
--------------------	--------------------	--------------------	--------------------



60737 : 2014-08-26	66028 : 2015-05-26	69312: 2015-08-29	69312 : 2015-10-03
71341 : 2016-02-28	71341 : 2016-03-01	71883 : 2016-04-05	73294 : 2016-05-14
77314 : 2016-12-28	M000000936: 2017-10-15	M000003152: 2018-01-27	

SM-9810OR

55258 : 2013-10-22	55665 : 2013-11-26	57707 : 2014-04-22	57526 : 2014-04-03
58739 : 2014-05-27	65264 : 2015-05-17		

SM-9810RE

55258 : 2013-10-22	55030 : 2013-10-22	56747 : 2014-03-04	57707 : 2014-04-22
58734 : 2014-05-27	58186 : 2014-05-12	65264 : 2015-05-17	65553 : 2015-05-30
70718 : 2016-01-09	71341 : 2016-03-01	74934 : 2016-08-19	75411 : 2016-09-15
75952 : 2016-10-17	77977 : 2017-01-12	79857 : 2017-04-28	81126: 2017-06-09
82216 : 2017-07-12	M000003152: 2018-01-27	M000003152 : 2018-3-31	M000005407: 2018-6-4
M000006370: 2018-7-28	M000006838: 2018-8-11		

SM-9810WH

55030 : 2013-10-01	55258 : 2013-10-22	56931 : 2014-03-15	59516 : 2014-07-02
60737 : 2014-09-30	66540 : 2015-07-15	73294 : 2016-05-14	75411 : 2016-09-17
77977 : 2017-01-12	83196 : 2017-08-12	M000001480: 2017-11-30	

SM-9810YE

55030 : 2013-10-01	56685 : 2014-03-04	58624 : 2014-06-10	65553 : 2015-05-25
68244: 2015-08-22	69067: 2015-08-13	69067 : 2015-10-01	69532 : 2015-11-21
71341 : 2016-03-01	75411 : 2016-09-15	76189 : 2016-10-25	78267 : 2017-02-25
82032 : 2017-06-27	M000003152: 2018-01-27	M000003262 : 2018-3-31	M000005842: 2018-6-23